


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None.

Index File No. X-19



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 1 1/4" x 30" galvanized pipe and brass cap marked: Set pipe 25" in the ground. From which by magnetic declination of N20°E:  
 A 15" Fir bears N54°E., 22.0 ft. scribed 1/4S35 BT.  
 A 12" Fir bears S18°E., 10.7 ft. scribed 1/4S35 BT.  
 Painted blazes red and 6" red band around. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Placed 54-4 on a steel fence post 5' west of the corner.

TLS R40E

1/4 — | — S35

OR PLS 1051  
1981

I hereby certify that the above corner monument was established as herein described.

Witnesses: Daniel Rowland  
Troy Phillips

July 30, 1981

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Barry B. Barbour*  
**OREGON  
OCT. 17, 1975  
BARRY B. BARBOUR  
1051**

Office of County Surveyor..... County of Union.....

State of Oregon....., I hereby certify that the within instrument was filed in this office

for record on the 10th day of August....., 19 81

*Howard L. Perry*  
(COUNTY OFFICIAL)

by *Barry B. Barbour*  
(DEPUTY)

**UNION COUNTY  
SURVEYOR**

Date Received \_\_\_\_\_  
 ☆ GPO-798-276

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 192-84 R