


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. X-21

**History of original corner establishment:**

Corner was originally established by Henry Meldrum, Deputy Surveyor, Under G.L.O. contract No. 450, during August 1882. Surveyors General's notes state: "Set post 3 ft. long, 3 ins. sq., 24 ins. in the ground, for 1/4 sec. cor., mkd. 1/S on W. face; from which a fir 10 ins. diam. bears S73°E., 18 lks. dist mkd. 1/4S BT. A fir 7 ins. diam. bears S78°W., 17 lks. dist. mkd. 1/4S BT."



**Description of corner evidence found:**

Found no trace of record post or BTs.

**Description of monument and accessories | established to perpetuate the original location of this corner:**

At surveyed point set 2 1/2" x 30" galvanized pipe and brass cap marked: Set pipe 25" in the ground. From which by magnetic declination of N20°E: An 18" Spruce bears S64°E., 21.5 ft. scribed 1/4S36 BT. A 22" Spruce bears N37°W., 52.4 ft. scribed 1/4S35 BT. Painted blazes red and 6" red band around. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Placed 54-4 on a steel fence post 5' south of the corner.

T1S R40E  
1/4  
S35 + S36  
OR PLS 1051  
1981

I hereby certivy that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland  
Troy Phillips

July 30, 1981

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Barry B. Barbour*

OREGON  
OCT. 17, 1975  
BARRY B. BARBOUR  
1051

Office of...County Surveyor..... County of...Union.....  
State of...Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the...10th day of...August....., 1981.  
*Howard L. Peery*..... by *Gary J. Langhit*  
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY  
SURVEYOR**

Date Received                     

Date Filed                     

By                     

File No. 193-84R