

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-07

History of original corner establishment:


Original corner established in 1898 by Alonzo Gesner under contract #683.

He set a Fir Post 4'x3½"x3½", 24" in ground.

From which:

An 8" White Fir bears N76°W, 13 lks.

A 7" White Fir bears S31½°E, 18 lks.



Description of corner evidence found:

No corner monument found.

BT's found:

A 20" White Fir bears N76°W, 13 lks, blaze healed.

A 17" White Fir bears S31½°E, 18 lks., blaze healed.

Description of monument and accessories established to perpetuate the original location of this corner:

Note: Corner falls in Eagle Cap wilderness area and was left undisturbed. A 60d spike was set at the corner location and was tied by traverse to section corner ½ mile west.

Follow 6200532 SE'ly from 6200530, ¼ mile to old saw mill landing. Walk East over summit of hill 600 ft. past summit. Corner is on edge of Minam breaks 400 ft. NE of toe of Mt. Moriah flat.

Compass Declination: 19½°E

Witness: Jeremy Sutton

I hereby certify that the above described corner evidence was found and evaluated as hereon described on Nov. 1, 1986.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

B. A. Sutton
OREGON
JULY 13, 1979
B. A. SUTTON
1848

**UNION COUNTY
SURVEYOR**

Date Received 12-5-86

Date Filed 12-5-86

By G. LANGLITZ DEPUTY

File No. 306-86R

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19....

..... by
(COUNTY OFFICIAL) (DEPUTY)