

Index

File No. E-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Trect or Survey No. _____

Cor. No. 522


T. 13 R. 71E

R.D. WALLOWA VALLEY County _____

Merid. Will

N.F. W-W State OR.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

ORIGINAL ROCK IN PLACE - DID NOT DISTURB

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DOWN 10" LARCH N73-30 E 28 SIDES
15" HIGH 30" PINE SNAG S 8 E 55 SIDES
DOWN 40" P. PINE S W 85 SIDES

CORNER IN FIR THICKET ABOUT 2-3
HUNDRED FT. WEST OF RIDGE TOP.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Signature WEIDMAN

Title _____

Division _____

Headquarters _____

Date _____

10-19-83

FS-7100-52 (3/68)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed _____

By _____

File No. 40-87R

E-21