CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. L-05

History of original corner establishment:

Original corner established in 1898 by Alonzo Gesner under contract #683. He set a Pine Post 4'x3"x3", 24" in ground. From which:

A 6" Spruce bears S64°E, 62 lks. A 6" Fir bears N89°W, 15 lks.

TIS R41E

Description of corner evidence found:

No corner monument found.

No bearing trees found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped: By single proportioning, set 2½"x30" aluminum capped aluminum pipe rising 6" above ground. Set steel fence post 3 ft. north of corner.

T1S R41E

S18 S17

RLS1848 1986

New BT's:

An 8" Spruce bears S79½°E, 39.3 ft., blazed&scribed: $\frac{1}{2}$ S17BT A 5" White Fir bears N44½°W, 77.7 ft., blazed&scribed: $\frac{1}{2}$ S18BT

Painted blazes and attached signs as required in Specifications for Cadastral Surveys, USFS Region 6, March,1982. A $\frac{3}{4}$ " brass disk stamped "RLS1848" nailed to lower end of blazes.

To find corner follow Rd. 6200610 Northeasterly 500 feet from 6200485. Corner is 160 ft. west across creek on easterly slope.

Compass Declination: 195°E Witness: Jeremy Sutton

I hereby certify that the above described corner monument and/or accessories was perpetuated as hereon described on Nov. 8, 1986. REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 13, 1979
B. A. SUTTON
County 4 8

Date Received 12-1-86

Date Filed 12-2-86

By G. LANGLITZ DEPUTY

File No. 287-86

UNION COUNTY

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276