CERTIFIED RECORD OF LAND CORNER MONUMENTATION

	N-13
Frequery of original corner establishment:	DIAGRAM
Corner established by Frank W. Campbell under Contract No. 468 dated April 12, 1883, pages 39 and 40, of the Government	T2 N R38E
Field Notes. North between Sections 21 and 22, variation 16^{0} East. 80.00 chains set a basalt stone $18" \times 10" \times 10"$ 12" in the ground marked three notches on the South and East edges.	2/122
A pine 26" in diam. bears N 70° E 160 lks. marked T 2N R 38E A fir 12" in diam. bears S 88° E 370 lks. marked T 2N R 38E A pine 30" in diam. bears S 31° W 225 lks. marked T 2N R 38E A fir 18" in diam. bears N 41° W 118 lks. marked T 2N R 38 E	S 21 BT.
This corner was set September 7, 1883.	
No record of subsequent remonumentation found in Cou	inty Records.
Description of corner evidence found:	
I found a rock mound that fits bearings, but no rock was found original description. (One rock that has approximately 1/3 brocould have fit the original description) but, the distances wou which is probably due to the BTs over sides of ridge where cor of ridge.	ld not intersect,
Found BTs:	with wisible but
A pine 25.5" in diam. bears N 70° E 105.6', standing dead word legible scribing. A fir 12" in diam. bears S 88° E 178.2', dead broken stump!	
but visible scribing. A pine 23.6" in diam. bears S 31° W 148.5', good BT with scribing A fir 18" in diam. bears N 41° W 77.88', dead tree. Wind he tree is rotting on the hillside with a reasonable stump he	ribing visible. as blown it down and
original location of this corner	mook mound around the
I set a $2\frac{1}{2}$ " x 30" iron pipe 1" in the ground and raised a 3' iron pipe with a brass cap marked as shown.	TOOK IIIOANA GEOGNO ON
From which I scribed new BTs: A pine 10" in diam. bears S 41° E 77.17' scribed T 2N R 38E A pine 16" in diam. bears N 76° E 131.44' scribed T 2N R 38 A fir 12" in diam. bears S 80° W 81.30' scribed T 2N R 38E I also used the pine 23.6" in diam. which bears S 31° W 148 BT and previously scribed N R 38E S 21.	S 22 BT. E S 15 BT. S 21 BT. .5' which was a good
I nailed BT posters and attention signs to BTs. I nailed a brass washer marked PLS 1097 to the BT blaze of BT	s
I set steel posts 15' North and 5' West with attention and be and raised rock mounds for each fence post. I painted a red band and painted the scribed blazes of BTs really a staff compass with 21° declination and a steel chair	ed. 72 N R 38 E
measuring all the distances horizontally. I painted all visible scribed blazes on the old existing BTs placed BT and attention signs on them.	61100
This corner was set September 21, 1979. Witness by Patrick Murphy and	1979
Deunifold Country SURVEYOR	PLS 1097
Office of County Surveyor County of Union	REGISTERED
State of Oregon , I hereby certify that Beter Received trument was fi	LAND SURVEY
for record on the day of	11 8
(COUNTY OFFICIAL) By	James H. Thursman
File No. <u>216 - 83</u> R	OREGON JULY 22, 1977 JAMES H. BUISMAN 1097
,	