


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner not previously established.

T 2 N R 38 E Q-21



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

Blaze line running North and South with Forest Service boundary tags on fence posts

SEE SURVEY NUMBER 023-2018

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED**

**TO MONUMENT THE LOCATION OF THIS CORNER:**

At position determined by survey, I set 5/8" x 30" iron pin, 28 inches in the ground, with a 2 1/2" aluminum cap marked as shown below, from which:


A 20" Ponderosa Pine bears North 6° East, a distance of 9.10 feet, marked S 1/16 S24 BT.  
A 22" Ponderosa Pine bears North 57° West, a distance of 7.85 feet, marked S 1/16 S23 BT.

Set steel fence post approx. 1' North

Corner falls approx. 200 ft. West of a forest rd.

I hereby certify that this monument was set June 12, 2018.

Witness: Kyle Tucker



REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Jeffrey S. Hsu*  
OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2019

**UNION COUNTY SURVEYOR**

Date Received 6/21/18

Date Filed 6/21/18

Filed By *ALG*

File Number 026-2018R

I use a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Distances are to a spike in the root crown of the trees. Bearings are to a brass washer in the lower blaze marked OPLS 83571.