


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

R-10

History of original corner establishment:

Corner not previously established.



Description of corner evidence found:

N/A

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*James H. Buisman*

OREGON  
JULY 22, 1977  
JAMES H. BUISMAN  
1097

Description of monument and accessories I established to perpetuate the original location of this corner

At the position described above, I set a 2½" aluminum cap on a 2½" x 30" aluminum pipe 528" in the ground marked as shown.

From which I scribed BTs:

- A fir 21" in diam. bears S 63°00' W 49.8' scribed W 1/16 S 28 BT.
- A fir 23" in diam. bears N 27°44' E 56.4' scribed W 1/16 S 21 BT.

I nailed a brass washer marked OPLS 1097 to BT blazes.


I set a steel fence post 5' South and 5' East with signs 54-2 and 54-4 and 54-4.

I painted a red band around BTs and face of scribe.

I used a steel tape and Wild T-2 and measured a horizontal distance to the center of the BTs.

This corner was set October 23, 1980. Witness by Patrick L. Murphy.

See map of survey.



Office of..... County of.....  
 State of....., I hereby certify that the within instrument was filed in this office  
 for record on the ..... day of.....  
 ..... by .....  
 (COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY  
SURVEYOR**

---

Date Received \_\_\_\_\_

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 222-83R