


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

U-12

History of original corner establishment:

Corner not previously established.



Description of corner evidence found:

N/A

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*James H. Buisman*

OREGON  
JULY 22, 1977  
JAMES H. BUISMAN  
1097

Description of monument and accessories I established to perpetuate the original location of this corner

At the position described above, I set a 2½" aluminum cap on a 2½" x 30" aluminum pipe 26" in the ground marked as shown.

From which I scribed BTs:

- A fir 11" in diam. bears N 01°09' E 33.8' scribed SE 1/16 S 28 BT.
- A fir 18" in diam. bears N 82°41' E 29.7' scribed SE 1/16 S 28 BT.

I nailed a brass washer marked OPLS 1097 to BT blazes.

I set a steel fence post 5' North with signs 54-2 and 54-4.


I set a fiberglass fence post 5' East with sign 54-2.

I painted a red band around BTs and face of scribe.

I used a steel tape and Wild T-2 and measured a horizontal distance to the center of the BTs.

This corner was set October 28, 1980. Witness by Patrick L. Murphy.

See map of survey.



Office of ..... County of .....  
 State of ....., I hereby certify that the within instrument was filed in this office  
 for record on the ..... day of .....  
 ..... by .....  
 (COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY  
SURVEYOR**

---

Date Received \_\_\_\_\_

Date Filed \_\_\_\_\_

By: \_\_\_\_\_ GPO 796 334

File No. 235-83R