CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.

4-14
DIAGRAM
2N 38E
5W1/16 34

Description of corner evidence found:

N/A

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 22, 1977
JAMES H. BUISMAN
1097

TLN R38E

SW/16 . 34

1980

109

Description of monument and accessories I established to perpetuate the original location of this corner

At the position described above, I set a $2\frac{1}{2}$ " aluminum cap on a $2\frac{1}{2}$ " x 30" aluminum pipe 25" in the ground marked as shown.

From which I scribed BTs:

A fir 6" in diam. bears S $68^{\circ}24$ ' E 7.4' scribed SW 1/16 S 34 BT. A fir 12" in diam. bears S $34^{\circ}02$ ' W 11.7' scribed SW 1/16 S 34 BT

I nailed a brass washer marked OPLS 1097 to BT blazes.

I set a steel fence post 5' North with signs 54-2 and 54-4.

I set a fiberglass fence post 5' East with signs 54-2.

I painted a red band around BTs and face of scribe.

I used a steel tape and Wild T-2 and measured a horizontal distance to the center of the BTs.

This corner was set October 29, 1980. Witness by Patrick L. Murphy.

See map of survey.

Office of	County o	d	
State of, I hereby	certify that the w	ithin Instrument was file	d in this office
for record on the day of	·		
	by		
(COUNTY OFFICIAL)	1	(DEPUTY)	
•		•	III

Form R6-7100-57 (9/71)

UNION COUNTY
Date Received
Date Filed
⊕ GPO 796-333