


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 2 N R 39 E A-02



DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

SEE SURVEY NUMBER 049-2018

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, 28" in the ground, with 2 1/2" aluminum cap marked as shown below marked as shown below, from which:

NEW BEARING OBJECTS:

A 20" White Fir bears North 42° East a dist. of 16.60 ft., marked W 1/16 S31 BT.
A 20" White Fir bears South 74° West a dist. of 17.05 ft., marked W 1/16 S6 BT.

Set steel fence post approx. 1 ft. South of monument.

I hereby certify that the corner was monumented on November 1, 2018.

Witness: Kyle A. Tucker and Keefe Doherty

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

BAGETT - GRIFFITH & BLACKMAN

T3N R39E

W 1/16 $\frac{S31}{S6}$

T2N

2018
OPLS 83571

**UNION COUNTY
SURVEYOR**

Date Received 11/28/18

Date Filed 11/28/18

Filed By [Signature]

File Number 062-2018R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distance is to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.