

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**


**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner originally established by Rufus Moore under GLO contract no. 382, dated March 23, 1881. Surveyor General field notes state:

Set post for 1/4 Sec. Cor., from which:  
A Tamarac 22 in. diam. bears N29°E, 38 lks. dist.  
A Tamarac 14 in. diam. bears S29°W, 35 lks. dist.

Surveys 034-2014 and 035-2014 find no remaining evidence of corner monument.

T 3 N R 39 E Z-15



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None.

SEE SURVEY NUMBER 066-2015

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED**

**TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At proportionate position, I set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap, marked as shown below, 27 inches in the ground, from which:


**NEW BEARING OBJECTS:**

A 5" Western Larch bears North 23° East, a distance of 49.80 feet, marked 1/4 S34 BT.  
A 4" Western Larch bears North 50° East, a distance of 32.40 feet, marked X BT.  
An 11" White Fir bears South 5° West, a distance of 76.70 feet, marked 1/4 S3 BT.  
An 8" Douglas Fir bears North 70° West, a distance of 139.70 feet, marked 1/4 S34 BT.  
No available trees in the Southeast quadrant.

Corner falls in a clearcut.

I hereby certify that the corner was monumented November 12, 2015.

**UNION COUNTY SURVEYOR**  
Date Received 11/20/15  
Date Filed 11/20/15  
Filed By [Signature]  
File Number 186-2015R



**REGISTERED PROFESSIONAL LAND SURVEYOR**  
[Signature]  
OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 15° East. Bearings are to a brass washer marked OPLS 83571 in the lower BT blaze. Distances are to at 60d spike in the right hand side of the tree.