
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T2N R39EB-17



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey Number: 022-2022

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, 28" in the ground, with a 2 1/2" aluminum cap marked as shown below, from which:

NEW BEARING OBJECT:

A 16" Ponderosa Pine bears North 45° East, a dist. of 69.30 feet scribed N1/16 S2 BT A 5" Alder bears North 63° West, a dist. of 3.25 feet scribed N1/16 S3 BT

Set steel fence post approx. 1 ft. South

Monument falls on North side of Easterly flowing Cabin Creek.

I hereby certify that the corner was monumented on July 6, 2022.


Witness: Kyle Tucker Dan Drum


REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU

Renewal Date: June 30, 2023

83571





I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.