CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Rufus Moore in GLO contract no. 382, dated March 23, 1881. Surveyor General field notes state:

Set post for 1/4 Sec Cor, from which: A tamarack 16 in diam bears N 67° E, 23 lks dist A fir 9 in diam bears N 29° W, 34 lks dist

T2N R39EC-17 S 3

DESCRIPTION OF CORNER EVIDENCE FOUND:

An existing prominent fence corner falls harmoniously with a proportionate position. From the fence corner, I find an old stump of indeterminate size, bearing N 29° W, a distance of 22 feet. I find no marks on the stump.

SEE SURVEY NUMBER 065-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the location of the fence corner, I set a $2 \ \mbox{\ensuremath{\mbox{\ensuremath}\ensuremath{\mbox{\ensuremath{\mbox{\ensuremath}\ensurema$ From which:

NEW BEARING TREES:

A 7" Douglas Fir bears North 37° East, a distance of 23.00 feet, marked 1/4 S2 BT.


A 3" Western larch bears South 60° East, a distance of 34.15 feet, marked X BT.

A 9" Douglas Fir bears South 79° West, a distance of 14.65 feet, marked 1/4 S3 BT. A 6" White Fir bears North 53° West, a distance of 23.55 feet, marked 1/4 S3 BT.

I set a steel fencepost approximately 1 foot North of the corner monument.


I hereby certify that the corner was monumented on October 29, 2015.

Witness: Thomas J. Kopp



REGISTERED **PROFESSIONAL** LAND SURVEYOR June 2, 2010 JEFFREY S. HSU 83571

Renewal Date: June 30, 2017



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 15° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.