


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Rufus Moore in GLO contract no. 382, dated March 23, 1881. Surveyor General field notes state:

Set post for 1/4 Sec. Cor, from which:
A Fir, 8 in. diam. bears S37°W, 17 lks. dist.
A Fir, 10 in. diam. bears N12°W, 24 lks. dist.

T 2 N R 39 E E-11



DESCRIPTION OF CORNER EVIDENCE FOUND:

Found remnants of an old rock jack. No discernable fence lines. Position of rock jack fits harmoniously with a proportionate position.

SEE SURVEY NUMBER 065-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position of the rock jack, I set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap, marked as shown below, 27 inches in the ground, from which:

NEW BEARING TREES:

- A 10" Western Larch bears North 19° East, a distance of 14.80 feet, marked 1/4 S4 BT.
- An 8" Western Larch bears South 85° East, a distance of 9.70 feet, marked 1/4 S9 BT.
- A 14" Ponderosa Pine bears South 63° West, a distance of 22.00 feet, marked 1/4 S9 BT.
- A 6" Western Larch bears North 56° West, a distance of 20.15 feet, marked 1/4 S4 BT.

I set a steel fence post approximately 1 foot North of the corner monument.
I hereby certify that the corner was perpetuated on October 26, 2015. Corner falls approximately 100 feet West of Darr Road.


UNION COUNTY SURVEYOR

Date Received 11/2/15

Date Filed 11/2/15

Filed By [Signature]

File Number 153-2015R



REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 15° East declination. The distances are to a 60d spike driven into the left side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.