
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Rufus Moore in GLO contract no. 382, dated March 23, 1881. Surveyor General field notes state:

Set post for cor. to secs. 2, 3, 10 and 11, from which: A Fir, 7 in. diam. bears N43°E, 15 lks. dist. A Fir, 5 in. diam. bears N30°W, 7 lks. dist. A Maple, 4 in. diam. bears S10°W, 44 lks. dist. A Fir, 8 in. diam. bears S65°E, 7 lks. dist.



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 065-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


At proportionate distance, I set a 2 $\frac{1}{2}$ " x 30" aluminum pipe with 2 $\frac{1}{2}$ " aluminum cap, marked as shown below, 28 inches in the ground, from which:

NEW BEARING TREES:

A 7" White Fir bears North 47° East, a distance of 23.90 feet, marked T2N R39E S2 BT. A 6" Douglas Fir bears South 72° East, a distance of 69.80 feet, marked T2N R39E S11 BT. A 5/8"x15" iron pin bears South 39°14' West, a distance of 15.35 feet, with 1 ½" aluminum cap marked BGB SURVEYORS SW RP. A 5/8"x15" iron pin bears North 63°26' West, a distance of 15.47 feet, with 1 ½" aluminum

cap marked BGBSURVEYORS NW RP.

Set a steel fencepost approximately 1 foot North of the corner monument. I hereby certify that the corner was perpetuated on October 30, 2015.




REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2017



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 15° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees. Basis of bearing to iron pin accessories is as per Survey Number 065-2015.