


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner not established.

T 2 N R 39 E F-03



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None.

See Survey Number 032-2019

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:**

At position by Survey I set a 5/8" x 30" iron pin, 27" in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

**NEW BEARING OBJECTS:**

An 8" Western Larch bears South 19° East a dist. of 5.95 ft., marked CN 1/16 S7 BT.  
A 5" Western Larch bears South 76° West a dist. of 7.20 ft., marked CN 1/16 S7 BT.

Set steel fence post approx. 1 ft. East

Falls approx. 5 ft. West of North/South running forest road.


I hereby certify that the corner was monumented on October 2, 2019.  
Witness: Kyle A. Tucker

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR



OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2021



**UNION COUNTY  
SURVEYOR**

Date Received 10/23/19

Date Filed 10/23/19

Filed By MSH

File Number 067-2019R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.