## UNION COUNTY SURVEYOR CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Survey Number 015-2005.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a  $5/8" \times 30"$  iron pin with 1 ½" aluminum cap marked as shown below, 28" in the ground, from which:

## NEW BEARING TREES:

An 8 inch diameter White Fir bears N  $56^{\circ}E$ , a distance of 26.30 feet, marked N1/16 S8 BT.

A 9 inch diameter Tamarack bears S  $39\,^{\circ}\text{W}$ , a distance of 20.90 feet, marked N1/16 S7 BT.


I hereby certify that the corner was monumented on July 6, 2005. Set steel fence post approximately 1 ft. North of monument. Witness: Greg Blackman Jr. and Rick Thew

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1989

RICK G. ROBINSON
2219

Renewal Date: December 31, 2006



T2N R39EF-05

8

S

## UNION COUNTY SURVEYOR Date Received 7/28/08 Date Filed By 4/2/106 Filed By 13-2065 R

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 17° East. The distance to the bearing trees is to a 50d spike driven on the right side of the tree at the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze.