UNION COUNTY SURVEYOR CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Survey Number 015-2005.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a $5/8" \times 30"$ iron pin with 1 ½" aluminum cap marked as shown below, 28" in the ground, from which:

NEW BEARING TREES:

A 14 inch diameter Tamarack bears N 59°E , a distance of 15.85 feet, marked CN1/16 S8 BT.

A 12 inch diameter Tamarack bears S $80\,^{\circ}\text{W}$, a distance of 13.60 feet, marked CN1/16 S8 BT.

I hereby certify that the corner was monumented on July 7, 2005. Set steel fence post approximately 1 ft. North of monument. Witness: Greg Blackman Jr. and Rick Thew

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON July 17, 1986

RICK G. ROBINSON 2219

Renewal Date: December 31, 2006

T 2 N R 39 E

C

N 1/16 S 8

C

2005

OPLS 2219

T2N R39EF-07

8

UNION COUNTY
SURVEYOR

blo I.

Date Filed O'0 100

Filed By Black

File Number 012-2005 R

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 17° East. The distance to the bearing trees is to a 50d spike driven on the right side of the tree at the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze.

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Survey 015-2005. Union County Monumentation Record 015-2005R states: At position by survey I set a 5/8" x 30" iron pin, 28" in

the ground, with 2 1/2" aluminum cap marked as shown below, from which:
A 14" Tamarack bears North 59° East a dist. of 15.85 ft.,

marked CN 1/16 S8 BT. A 12" Tamarack bears South 80° West a dist. of 13.60 ft., marked CN 1/16 S8 BT.

Set steel fence post approx. 1 ft. North.



T 2 N R 39 E F-07

DESCRIPTION OF CORNER EVIDENCE FOUND:

A 5/8" iron pin, flush with the ground, with 2 1/2" aluminum

cap marked as shown below, from which:
A 17" Tamarack stob bears North 59° East a dist. of 15.85 ft., dead and standing 7' tall with healed blaze.

A 12" Tamarack bears North 80° West a dist. of 13.60 ft., dead and standing 7' tall with scribes visible on a partially healed blaze.

Steel fence post bears approx. 1 ft. North

See Survey 032-2019

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

From Aluminum Cap,

NEW BEARING OBJECTS:


A 12" White Fir bears North 74° East a dist. of 28.50 ft., marked CN 1/16 S8 BT. A 4" Western Larch bears South 7° West a dist. of 15.05 ft., marked CN 1/16 S8 BT.

I hereby certify that the corner was perpetuated on October 8, 2019.

Witness: Kyle A. Tucker

REGISTERED PROFESSIONAL LAND SURVEYOR OREGON June 2, 2010 JEFFREY S. HSU 83571

Renewal Date: June 30, 2021



UNION COUNTY SURVEY

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.