## UNION COUNTY SURVEYOR

## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Survey Number 015-2005.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a  $5/8" \times 30"$  iron pin with 1 ½" aluminum cap marked as shown below, 26" in the ground, from which:

## NEW BEARING TREES:

A 12 inch diameter Ponderosa Pine bears N  $69^{\circ}\text{E}$ , a distance of 35.80 feet, marked N1/16 S9 BT.

A 14 inch diameter Douglas Fir bears N  $12\,^{\circ}\text{W}$ , a distance of 49.40 feet, marked N1/16 S8 BT.

Raised small mound of stone around monument. Set steel fence post approximately 1 ft North of monument.


I hereby certify that the corner was monumented on June 28, 2005. Witness: Greg Blackman Jr. and Mark Brooks

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1996
RICK G. ROBINSON

Renewal Date: December 31, 2006

2219



T2N R39EF-09

8

UNION COUNTY
SURVEYOR

Date Received 7/28/05

Date Filed 8/8/05

Filed By Hym 7. Blesser

File Number 016-2005 R

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 17° East. The distance to the bearing trees is to a 50d spike driven on the right side of the tree at the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze.