


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner not previously established

T 2 N R 39 E F-11



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None

SEE SURVEY NUMBER 065-2015

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At the position determined by survey, I set a 5/8" x 30" iron pin, with a 2 1/2" aluminum cap, marked as shown below, 27" in the ground in the root crown of a large tree. From which:

**NEW BEARING TREES:**

An 8" White Fir bears South 38° East, a distance of 52.55 feet, marked CN 1/16 S9 BT.  
An 11" White Fir bears North 45° West, a distance of 2.15 feet, marked CN 1/16 S9 BT.

I set a steel fencepost approximately 1 foot South of the corner monument.

I hereby certify that the corner was monumented on October 29, 2015.

Witness: Thomas J. Kopp


**UNION COUNTY SURVEYOR**

Date Received 11/2/15

Date Filed 11/2/15

Filed By [Signature]

File Number 156-2015R



REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]

OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 15° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.