


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 2 N R 39 E G-11



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 065-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 2 1/2" aluminum pipe with a 2 1/2" aluminum cap, marked as shown below, 26" in the ground with a collar of stone 1 foot diameter. From which:

NEW BEARING TREES:

- A 6" Western Larch bears North 61° East, a distance of 21.70 feet, marked C 1/4 S9 BT.
- A 6" Western Larch bears South 66° East, a distance of 28.90 feet, marked C 1/4 S9 BT.
- A 5" Western Larch bears South 73° West, a distance of 10.45 feet, marked C 1/4 S9 BT.
- A 5" Western Larch bears North 30° West, a distance of 24.85 feet, marked C 1/4 S9 BT.

I set a steel fencepost approximately 1 foot North of the corner monument.

I hereby certify that the corner was monumented on October 27, 2015.

Witness: Thomas J. Kopp


UNION COUNTY SURVEYOR

Date Received 11/2/15

Date Filed 11/2/15

Filed By [Signature]

File Number 157-2015R



REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 15° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.