


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Rufus Moore in GLO contract no. 382, dated March 23, 1881. Surveyor General field notes state:

Set post for 1/4 Sec Cor, from which:
A pine 5 in diam bears S 72° E, 9 lks dist
A tamarack 20 in diam bears N 79° W, 20 lks dist

T 2 N R 39 E G-17



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 065-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the proportionate position, I set a 2 1/2" x 30" aluminum pipe, with a 2 1/2" aluminum cap, marked as shown below, 26" in the ground with a collar of stone 1.5 feet diameter.
From which:

NEW BEARING TREES:


A 14" Western Larch bears North 80° East, a distance of 52.85 feet, marked 1/4 S11 BT.
A 9" Western Larch bears South 13° East, a distance of 56.85 feet, marked 1/4 S11 BT.
A 12" Western Larch bears South 57° West, a distance of 29.10 feet, marked 1/4 S10 BT.
A 3" Western Larch bears North 29° West, a distance of 36.45 feet, marked X BT.

I set a steel fencepost approximately 2.5 feet North of the corner monument.

I hereby certify that the corner was monumented on October 29, 2015.

Witness: Thomas J. Kopp

UNION COUNTY SURVEYOR
Date Received 11/2/15
Date Filed 11/2/15
Filed By [Signature]
File Number 169-2015R



REGISTERED PROFESSIONAL LAND SURVEYOR
[Signature]
OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 15° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.