


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Rufus Moore in GLO contract no. 382, dated March 23, 1881. Surveyor General field notes state:

Set post for cor. to secs. 9, 10, 15 and 16, from which:
A pine 32 in diam bears N 68° E, 56 lks dist
A tamarack 4 in diam bears N 58° W, 12 lks dist
A tamarack 4 in diam bears S 48° W, 10 lks dist
A tamarack 4 in diam bears S 37° E, 11 lks dist

T 2 N R 39 E J-13



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 065-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the proportionate position, I set a 2 1/2" x 30" aluminum pipe, with a 2 1/2" aluminum cap, marked as shown below, 29" in the ground. From which:

NEW BEARING TREES:


An 8" White Fir bears North 66° East, a distance of 39.25 feet, marked T2N R39E S10 BT.
A 4" Western Larch bears South 37° East, a distance of 46.05 feet, marked X BT.
An 8" Douglas Fir bears South 78° West, a distance of 36.35 feet, marked T2N R39E S16 BT.
A 6" Ponderosa Pine bears North 35° West, a distance of 37.85 feet, marked T2N R39E S9 BT.

I set a steel fencepost approximately 1 foot North of the corner monument.

I hereby certify that the corner was monumented on October 28, 2015.

Witness: Thomas J. Kopp

UNION COUNTY SURVEYOR
Date Received 11/2/15
Date Filed 11/2/15
Filed By [Signature]
File Number 160-2015R



REGISTERED PROFESSIONAL LAND SURVEYOR
[Signature]
OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 15° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.