
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Rufus Moore in GLO contract no. 382, dated March 23, 1881. Surveyor General field notes state:

Set post for 1/4 Sec Cor, from which: A tamarack 10 in diam bears N 10° E, 19 lks dist A pine 16 in diam bears S 19° W, 18 lks dist



DESCRIPTION OF CORNER EVIDENCE FOUND:

Mone

SEE SURVEY NUMBER 065-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the proportionate position, I set a 2 $\frac{1}{2}$ " x 30" aluminum pipe, with a 2 $\frac{1}{2}$ " aluminum cap, marked as shown below, 28" in the ground with a collar of stone 1.5 feet diameter. From which:

NEW BEARING OBJECTS:

An 11" White Fir bears North 70° East, a distance of 41.95 feet, marked 1/4 S10 BT. A 3" Ponderosa Pine bears South 82° East, a distance of 4.90 feet, marked X BT. An 8" Douglas Fir bears South 15° West, a distance of 39.55 feet, marked 1/4 S15 BT. A 5/8" x 30" iron pin bears North 43° 23' West, a distance of 20.21 feet, marked NW RP.

I set a steel fencepost approximately 1 foot North of the corner monument.

Corner falls approximately 100 feet East of a North/South running logging road.

I hereby certify that the corner was monumented on October 28, 2015.

Witness: Thomas J. Kopp

UNION COUNTY
SURVEYOR

Date Received 11715

Date Filed By 1215

File Number 161-7015 R

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

S10
1/4

S15

2015

OPLS 83571

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 15° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees. Basis of bearings to the iron pin accessory are as per Survey Number 065-2015.