


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Rufus S. Moore under GLO contract number 382, dated March 23rd, 1881. GLO record states:

- Set post for 1/4 Sec. Cor., from which:
- A Fir, 7 in. diam. bears N42°E, 30 lks. dist.
- A Fir, 9 in. diam. bears S73°W, 23 lks. dist.

T 2 N R 39 E L-01



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 024-2013

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position, I set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap, marked as shown below, 29 inches in the ground, in a collar of stone 1 ft. diam., from which:


- A 13 inch Douglas Fir bears North 16° East, a distance of 13.10 feet, marked 1/4 S18 BT.
- A 6 inch Douglas Fir bears South 48° East, a distance of 51.30 feet, marked 1/4 S18 BT.
- A 9 inch White Fir bears South 14° East, a distance of 38.80 feet, marked 1/4 S18 BT.
- A 9 inch White Fir bears North 76° West, a distance of 19.10 feet, marked 1/4 S13 BT.

I hereby certify that the corner was monumented on May 21, 2013.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

[Signature]
OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015



I used a steel tape and magnetic compass in the establishment of the accessories. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing tree.

UNION COUNTY SURVEYOR

Date Received 6/3/13
Date Filed 6/3/13
Filed By [Signature]
File Number 416-2013R