


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 2 N R 39 E L-15



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 065-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 2 1/2" aluminum pipe with a 2 1/2" aluminum cap, marked as shown below, 28" in the ground. From which:

NEW BEARING TREES:

- A 9" White Fir bears North 72° East, a distance of 14.55 feet, marked C 1/4 S15 BT.
- A 6" White Fir bears South 36° East, a distance of 35.15 feet, marked C 1/4 S15 BT.
- A 4" Spruce bears South 5° West, a distance of 12.00 feet, marked X BT.
- A 6" White Fir bears West, a distance of 17.00 feet, marked C 1/4 S15 BT.

I set a steel fencepost approximately 1 foot North of the corner monument.

Corner falls 16.5 feet Northerly of a fence corner, fences bears South and West.

I hereby certify that the corner was monumented on October 29, 2015.

Witness: Thomas J. Kopp


UNION COUNTY SURVEYOR

Date Received 11/2/15

Date Filed 11/2/15

Filed By [Signature]

File Number 16A-2015R



REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 15° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.