CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:	
Center East 1/16th corner, Section 13, T2N, R39E, W.M., Union County, Oregon	
None	
Description of corner evidence found: None	REGISTERED PROFESSIONAL LAND SURVEYOR OREGON JULY 13, 1979 R. A. SUTTON 1848 EUGUAL 6/3098
Description of monument and accessories I established to perpetuate to original location of this corner:	
I set a 5/8"x30" iron rod with a 1-1/2" aluminum cap marked:	C = 1/16 C S13 RLS 1848 1987
at the proportioned location between the computed center 1/4 to the West and the proportioned location of the 1/4 corner to the East.	
I established the following references: A 16" Ponderosa Pine bears N38°15'E, 30.6' blazed & scribed (CE1/A 13" Douglas Fir bears N44°30'W, 39.1' blazed & scribed (CE1/16)	
Office of the County Surveyor County of Union	dinthia office Union COUNTY
State of Oregon, I hereby certify that the within instrument was file	SURVEYOR
for record on the day of	
(COUNTY OFFICIAL) by	Date Filed 10/15-196
(OCOLITE OTTEORIE)	Date liled 10/15-196