

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Southwest 1/16 corner, Section 13, T2N, R39E, W.M., Union County, Oregon

None

Description of corner evidence found:

None

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*B. A. Sutton*  
OREGON  
JULY 13, 1979  
B. A. SUTTON  
1848

RENEWAL 6/30/96

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a 5/8"x30" iron rod with a 1-1/2" aluminum cap marked:  
at the center of the Southwest quarter of section 13.

SW 1/16 S13  
RLS 1848  
1987

I established the following references:

- A 8" Ponderosa Pine bears N46°E, 16.4' blazed & scribed (SW1/16S13BT)
- A 14" Douglas Fir bears S2°15'E, 10.3' blazed & scribed (SW1/16S13BT)

Office of the \_\_\_\_\_ County Surveyor \_\_\_\_\_ County of \_\_\_\_\_ Union \_\_\_\_\_

State of Oregon, I hereby certify that the within instrument was filed in this office

for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_\_

\_\_\_\_\_ by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)

RECEIVED	COUNTY CLERK
Date Received	9/18/96
Date Filed	10/13/96
By	<i>Mary T. Blawie</i>
File No.	100-1996R