CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T 2 N R 39 E N-14

DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 024-2017

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At point 4 ft. South of a position determined by survey, I set a $5/8" \times 30"$ iron pin, 26" in the ground with 2 4" Aluminum cap marked as shown below, from which:

NEW BEARING TREES:

A 8" White Fir bears South 31° East, a distance of 11.40 feet, marked W 1/16 S22 BT. A 7" White Fir bears North 22° West, a distance of 29.50 feet, marked W 1/16 S15 BT.

Set steel fencepost 1 ft. North of monument

True corner position falls on cut bank of Kingsbury Road.

PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

WC WC Style T2N R39E T2N R39E T2N R39E S15 S22 OPLS 83571 4 FT ^

UNION COUNTY
SURVEYOR

Date Received 6/22/17

Date Filed By 6/22/17

Filed By 6/22/17

File Number 01/-2017 R

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Bearings are to a brass washer marked OPLS 83571 in the lower blaze of the tree. Distance is to a spike set in the root crown of the side of the tree.