CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

A post was set for the $\frac{1}{4}$ corner from which the following bearing trees were set:
A pine 36" dia. bears North 18 lks. scribed \$\frac{1}{4}\$ S BT.
A pine 10" dia. bears S 15 W, 61 lks. scribed \$\frac{1}{4}\$ S BT.

| <i>N</i> · | N-15 | | |
|------------------|------|--|--|
| DIAGRAM | Z | | |
| T 2 N S 15 | | | |
| * S 22 R 39 E | | | |

Description of corner evidence found:

No evidence was found.

Description of monument and accessories Lestablished to perpetuate the original location of this corner:

Established the location of the \$\frac{1}{4}\$ corner by proportionate measurements. I set a 5/8" x 30" iron pin with a cap stamped RLS 645 in a mound of stone. I then set new bearing trees as follows:

A pine 7" dia., which bears S 00 47 W, 56.6 feet, scribed \$\frac{1}{4}\$ S S 22 BT. A pine 10" dia. which bears N 17 55 E, 90.7 feet, scribed \$\frac{1}{4}\$ S S 15 BT.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

12-20-77 OREGON JAMES H. HAMBLETON 645

AHa.

| Office of | Coun | ty of | 7 | |
|-------------------|------|-------------------------------------|--------------|--------------------|
| • | | ty ofwithin instrument was filed in | | SAEAOB A COMMAA |
| (COUNTY OFFIC) | Al) | (DEPUTY) | Date Receive | ed |
| 6 7100 67 (0 /71) | • | | | |

Form R6-7100-57 (9/71)

File No. 275-83R

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Rufus S. Moore under GLO contract Number 382, dated March 23, 1881. Surveyor General record states: Set post for 1/4 Sec Cor, from which:

A pine 36 in diam bears North, 18 lks dist A pine 10 in diam bears S 15° W, 61 lks dist

In Survey Number 108-77, James H. Hambleton finds no original evidence and resets this corner at the proportionate position. Union County Monumentation record states:

Established the location of the 1/4 corner by proportionate measurements. I set a 5/8" x 30" iron pin with a cap

stamped RLS 645 in a mound of stone. I then set new bearing trees as follows: A pine 7" dia., which bears S 00 47 W, 56.6 feet, scribed 1/4 S S 22 BT. A pine 10" dia. which bears N 17 55 E, 90.7 feet, scribed 1/4 S S 15 BT.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a 2 1/2" brass cap, marked as shown below, in a 1.5 foot diameter collar of stone, from

A 17" Ponderosa Pine bears South, a distance of 56.6 feet, alive and vigorous with a healed blaze.

SEE SURVEY NUMBER 065-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

From the brass cap monument

NEW BEARING TREES:

A 13" Ponderosa Pine bears North 64° East, a distance of 9.45 feet, marked 1/4 S15 BT. A 13" Ponderosa Pine bears South 64° West, a distance of 22.70 feet, marked 1/4 S22 BT. A 3" Ponderosa Pine bears North 10° West, a distance of 38.75 feet, marked X BT.

Set a steel fencepost approximately 1 foot North of corner monument. I hereby certify that the corner was perpetuated on October 22, 2015.

Witness: Thomas J. Kopp

REGISTERED **PROFESSIONAL** LAND SURVEYOR DREGON June 2, 2010 JEFFREY S. HSU

83571 Renewal Date: June 30, 2017

T₂N **S15** 1/4 S22 **R39E** 1977

T2N R39EN-15

15

S

UNION COUNTY **SURV** File Number 167-2015R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 15° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.