

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Section corner common to Sections 13, 14, 23 & 24, T2N, R39E, W.M., Union County, Oregon.

Original corner established in 1881 by R. Moore under contract No. 382 approved 3/23/1881. He set a post for the section corner common to sections 13, 14, 23 & 24 from which:

- A Pine 26" in diameter bears N57°E, 87 Lks. distance.
- A Pine 34" in diameter bears N38°W, 67 Lks. distance.
- A Pine 24" in diameter bears S20°W, 16 Lks. distance.
- A Pine 34" in diameter bears S72°E, 41 Lks. distance.

REGISTERED PROFESSIONAL LAND SURVEYOR

B. A. Sutton

OREGON
JULY 13, 1979
B. A. SUTTON
1848


RENEWAL 6/30/98

Description of corner evidence found:

No original corner evidence was found. Found a 24" Pine stump with blaze visible (BT at the base) bears S20°W, 16 Lks.

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a 5/8"x30" iron rod with a 1-1/2" aluminum cap marked: at N20°E, 16 Lks. from the above described original bearing tree stump.



I established the following references:

- A 13" Ponderosa Pine bears N27°E, 7.8' blazed & scribed; (T2NR39ES13BT)
- A 12" Ponderosa Pine bears S48°30'E, 16.6' blazed & scribed; (T2NR39ES24BT)
- A 6" Western Larch bears S49°W, 34.6' blazed & scribed; (T2NR39ES23BT)
- A 13" Ponderosa Pine bears N33°30'W, 5.1' blazed & scribed; (T2NR39ES14BT)

Office of the _____ County Surveyor _____ County of _____ Union _____
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the _____ day of _____, 19 _____

_____ by _____
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received 9/16/86

Date Filed 10/5/86

By [Signature]

File No. 102-1996R