
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T2N R39EO-16



DESCRIPTION OF CORNER EVIDENCE FOUND:

None .

SEE SURVEY NUMBER 024-2017

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, 29" in the ground with a 2 $\frac{1}{2}$ " Aluminum cap marked as shown below, from which:

NEW BEARING TREES:

An 8" Douglas Fir bears North 79° East, a distance of 31.65 feet, marked NE 1/16 S22 BT. A 12" Douglas Fir bears North 49° West, a distance of 22.40 feet, marked NE 1/16 S22 BT.

Set a steel fencepost North approx. 0.5 ft.

I hereby certify that the corner was monumented June 12, 2017. Witness: Kyle Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

OPLS 83571

UNION COUNTY SURVEYOR

6/77/1

Date Filed 6/77/17

File Number 014-2017 K

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Bearings are to a brass washer marked OPLS 83571 in the lower blaze of the tree. Distance is to a spike set in the root crown of the side of the tree.