


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

P-17

History of original corner establishment:

A wooden post was set for this $\frac{1}{4}$ corner from which the following bearing trees were set:
A pine 40" dia. bears N 27 W, 45 lks.
A pine 36" dia. bears S 20 E, 33 lks.



Description of corner evidence found:

Found charred stump of 40" pine and badly rotted uprooted pine approx. 36" dia. lying on the ground. By retracing the original line could verify these trees as being the original bearing trees, as they fit the GLO calls.

Description of monument and accessories established to perpetuate the original location of this corner

Located the $\frac{1}{4}$ corner using the GLO calls and set a 5/8" x 30" iron pin with a cap stamped RLS 645 in a mound of stone. I then set two new bearing trees as follows:

A douglas fir 7" dia. which bears S 62 W, 48.3 feet scribed $\frac{1}{4}$ S S 22 BT.

A douglas fir 6" dia. which bears N 50E, 19.8 feet scribed $\frac{1}{4}$ S S 23 BT.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James H. Hambleton
12-30-77

OREGON
JULY 10, 1964
JAMES H. HAMBLETON
645

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the day of.....
..... by.....
(COUNTY OFFICIAL) (DEPUTY)

| | |
|------------------------------|----------------|
| UNION COUNTY SURVEYOR | |
| Date Received | _____ |
| Date Filed | _____ |
| By | _____ |
| File No. | <u>281-83R</u> |

* GPO 796-333