

CERTIFIED RECORD OF LAND CORNER MONUMENTAL

History of original corner establishment:

1/4 corner common to Sections 23 & 24, T2N, R39E, W.M., Union County, Oregon.

Original corner established in 1881 by R. Moore under contract No. 382 approved 3/23/1881. He set a post from which:
A Pine 40" diameter bears S13°E, 58 Lks. distance
A Pine 9" diameter bears S33°W, 59 Lks. distance

REGISTERED PROFESSIONAL LAND SURVEYOR

B. Sutton
OREGON
JULY 13, 1979
R. A. SUTTON
1848


RENEWAL 6/30/78

Description of corner evidence found:

No original corner evidence found. The following corner reference was found: A stump hole with rotted remains of portion of blaze overgrowth bears S33°W, 59 Lks. (1/4S) visible.

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a 5/8"x30" iron rod with a 1-1/2 inch aluminum cap marked: at N33°E, 59 Lks from the above described original Section 23 bearing tree evidence.



I established the following references:
A 13" Douglas Fir bears S51°E, 68.5' blazed & scribed (1/4S24BT)
A 12" Douglas Fir bears S25°15"W, 28.1' blazed & scribed (1/4S23BT)

Office of the _____ County Surveyor _____ County of _____ Union _____

State of Oregon, I hereby certify that the within instrument was filed in this office

for record on the _____ day of _____, 19 _____

_____ by _____
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Date Received 9/16/96
Date Filed 10/5/96
By *Hyun T. Blum*
File No. 105-1986R