CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

None.

T 2 N R 39 E Q-05

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 024-2013

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8"x30" iron pin with 2 ½" aluminum cap, marked as shown below, 29 inches in the ground, from which:

- A 7 inch White Fir bears South 60° East, a distance of 23.05 feet, marked S 1/6 S20 BT.
- A 4 inch White Fir bears North 18° West, a distance of 13.00 feet, marked X BT.
- I hereby certify that the corner was monumented on May 30, 2013.

PROFESSIONAL LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571


Renewal Date: June 30, 2015

UNION COUNTY
SURVEYOR

Date Received 6/3/3

Date Filed 6/3/3

Filed By 4/3-20/3R



I used a steel tape and magnetic compass in the establishment of the accessories. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing tree.