


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

None Established

T 2 N R 39 E Q-16



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 049-2017

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin with 2 1/2" aluminum cap marked as shown, 26" in the ground with collar of stone 1 ft. diam.,

from which:

NEW BEARING TREES:

A 10" Ponderosa Pine bears North 38° East, a distance of 29.90 feet, marked SE 1/16 S22 BT.
A 6" Ponderosa Pine bears South 27° East, a distance of 17.45 feet, marked SE 1/16 S22 BT.

Set steel fencepost approx. 1 ft. South of monument.

North/South bearing fence bears East approx. 5' of monument

I hereby certify that the corner was monumented December 7, 2017.

Witness: Kyle Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

BAGETT - GRIFFITH & BLACKMAN

T2N R39E

SE 1/16 S22

2017

OPLS 83571

UNION COUNTY
SURVEYOR

Date Received 12/14/17

Date Filed 12/14/17

Filed By [Signature]

File Number 054-2017R

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Bearing is to a brass washer marked OPLS 83571 in the lower blaze of the tree. Distance is to a spike set in the root crown of the side of the tree.