## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by General Land Office contract survey.

Original survey record states; Set a post from which; A pine 36" in diam bears S57°W 33 lks dist; A tamarack 16" in diam bears N45°W 18 lks dist;

R-7	
DIAGRAM	
T2N	R39EWM
S20 S29	

Description of corner evidence found:

found a small slab with a  $^{\rm WBM}$  scribed on it at a pine stump which bears  $557^{\rm eW}$  33 lks dist;

REGISTERED
OREGON
LAND SURVEYOR

MAY 4, 1956
JAMES G. VOELZ
381

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 2" galvanized pipe 30" long with an 8" plated welded to bottom and galvanized cap on top. The pipe set to a depth of 24" and back filled with tamped soil.

† Cor T2N R39E

I stamped the disk

From the pipe the original bearing tree is; A pine stump bears S57°W 33 lks dist;

\$20 \$29 Oreg Lic 381 1970

File No. 326-84 R.

I established new bearing trees as follows; A fir 14" in diam bears N31°E 20.7' scribed \$SBT A ponderosa pine 13" in diam bears S42°E 22.6 ft scribed \$SBT;

Office of County surveyor County of Union State of Oregon , I hereby certify that the within instrument was filed in		was filed in this official COUNTY
or record on the 26 day of June County surveyor	10 70 a 2	o'elack, P. h., (signed) RVEYOR
(COUNTY OFFICIAL)		Date Received
	L	Date Filed