CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishments

A wooden post was set for this section corner from which the following bearing trees were set:
A pine 40" dia. bears N 58 E 47 lks.
A pine 44" dia. bears N 45 W 9 lks.
A pine 24" dia. bears S 76 W 129 lks.
A pine 26" dia. bears S 71 E 206 lks.

		R	- 13	
DIAGRAM				9
	T :	2 N		
S	21	S	22	
s	28	S	27	
	R	39 E		

Description of corner evidence found:

Found evidence of charred 44" pine stump and evidence of stumps and stump holes of remaining bearing trees which fit the descriptions set forth in the GLO notes, though I found no scribing.

Description of monument and accessories I established to perpetuate the original location of this corner

Restored the section corner by using the GLO call distance and bearings. Set a 5/8" x 30" iron pin with a cap stamped RLS 645 in a large mound of stone. I then set four new bearing trees as follows:

A pine 14" dia. which bears N O4 W, 119.9 feet scribed T 2 N R 39 E S 21 BT.

A pine 10" dia. which bears S 28 W, 71.8 feet scribed T 2 N R 39 E S 28 BT.

A pine 14" dia. which bears S 76 E, 122.8 feet scribed T 2 N R 39 E S 27 BT.

A pine 12" dia. which bears N 44 E, 102.2 feet scribed T 2 N R 39 E S 22 BT.

REGISTERED **PROFESSIONAL** LAND SURVEYOR and Athanth 12-20-77 OREGON JULY 10, 1964 JAMES H. HAMBLETON 645 State of....... , I hereby certify that the within Instrument was filed in this office for record on the day of

(DEPUTY)

Form R6-7100-57 (9/71)

(COUNTY OFFICIAL)

ANDAEAOS ANION CORMAA	
Date Received	
Date Filed	
☆ GPO 796-333	
He No. 285-83R	

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Rufus Moore in GLO contract no. 382, dated March 23, 1881. Surveyor General field notes state:

Set post for Cor to Secs. 21, 22, 27 and 28, from which: A pine 40 in. diam. bears N58°E, 47 lks. dist. A pine 44 in. diam. bears N45°W, 9 lks. dist.

A pine 24 in. diam. bears S76°W, 129 lks. dist. A pine 26 in. diam. bears S71°E, 206 lks. dist.

In Survey Number 108-77, James Hambleton monuments the corner from original evidence. From which:

A 14" Pine bears N4°W, 119.9 ft.

A 12" Pine bears N44°W, 102.2 ft. A 14" Pine bears S76°E, 122.8 ft. A 10" Pine bears S28°W, 71.80 ft.

Corner as per Hambleton, is found and accepted by Barry Barbour in Survey Number 33-79.

S 27

T2N R39E R-13

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a 1" O.D. iron pipe, 3 in. above ground, in a collar of stone, 3 ft. diam., from which:

A 24" Fir stump bears South 76° East, a distance of 122 ft, with healed blaze evident. A 17" Ponderosa Pine bears South 28° West, a distance of 71.8 ft. alive and vigorous with healed blaze.

SEE SURVEY NUMBER 025-2014

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

From the iron pipe,

NEW BEARING TREES:

A 10" Ponderosa Pine bears North 68° East, a distance of 25.60 feet, marked T2N R39E S21 BT. A 7" Ponderosa Pine bears South 38° East, a distance of 31.40 feet, marked T2N R39E S27 BT. A 9" Ponderosa Pine bears North 9° West, a distance of 40.05 feet, marked T2N R39E S22 BT.

Corner falls 1.5 feet South of an East/West fenceline. I hereby certify that the corner was perpetuated on August 21, 2014.

Witness: Thomas J. Kopp

UNION COUNTY SURVEYOR File Number 032-2014

> REGISTERED **PROFESSIONAL** LAND SURVEYOR OREGON June 2, 2010 JEFFREY S. HSU

83571 Renewal Date: June 30, 2015 I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.