CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T2N R39ER-14 27 S

DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 025-2014

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, 24 inches in the ground, with 2 ½" aluminum cap marked as shown below, from which:

An 8 inch Ponderosa Pine bears South 8° East, a distance of 44.80 feet, marked W 1/16 S27

An 11 inch Ponderosa Pine bears West, a distance of 31.00 feet, marked W 1/16 S22 BT.

Set a steel fencepost approximately 1 foot North of corner monument. Corner falls approximately 9.5 feet North and 7.6 feet East of a fence corner. I hereby certify that the corner was monumented on August 28, 2014.

Witness: Thomas J. Kopp


UNION COUNTY **SURVEYOR**

> REGISTERED **PROFESSIONAL** LAND SURVEYOR

ne 2, 2010 JEFFREY S. HSU 83571

OREGON

Renewal Date: June 30, 2015



I used a steel tape and magnetic compass in the establishment of the accessories. I used 16° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the bearing trees.