
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

None Established

T2N R39ER-18



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 049-2017

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin with 2 ½" aluminum cap marked as shown, 25" in the ground with collar of stone 2 ft. diam.,

from which:

NEW BEARING TREES:

A 20" Ponderosa Pine bears North 8° East, a distance of 44.85 feet, marked W 1/16 S23 BT. An 18" Ponderosa Pine bears South 4° West, a distance of 18.20 feet, marked W 1/16 S26 BT.

East/West fence bears approx. 1' North of monument

North/South bearing fence bears approx. 15' West of monument

I hereby certify that the corner was monumented December 7, 2017.

Witness: Kyle Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

 $\frac{1}{\sqrt{2}}$ T2N R39E $\frac{1}{\sqrt{2}}$ W 1/16 $\frac{\frac{523}{526}}{2017}$ OPLS 83571

UNION COUNTY
SURVEYOR

Date Received 12/14/17

Date Filed By 12/14/17

File Number 057-2017

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Bearing is to a brass washer marked OPLS 83571 in the lower blaze of the tree. Distance is to a spike set in the root crown of the side of the tree.