


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner established by James Hambleton in Survey Number 82-78. No description of corner monument. Additional monuments set as property pins fall South 0°11'13" West, 66.00 feet and North 89°36' East, 264.0 feet.

T 2 N R 39 E S-16



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None. From true corner position, as determined by survey:

A 5/8" iron pin bears South 3°19'42" East, a distance of 65.78 feet, set by Survey Number 82-78.

A 5/8" iron pin bears North 89°23'08" East, a distance of 268.26 feet, set by Survey Number 82-78.

SEE SURVEY NUMBER 025-2014

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED**

**TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At position determined by survey, I set a 5/8" x 30" iron pin, 27 inches in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

A 15 inch Ponderosa Pine bears South 42° East, a distance of 16.50 feet, marked NE 1/16 S27 BT.

A 9 inch Ponderosa Pine bears South 56° West, a distance of 46.10 feet, marked NE 1/16 S27 BT.

Corner falls 2 feet South of and East/West fenceline, and 28.3 feet West of a fence corner. I hereby certify that the corner was monumented on August 28, 2014.

Witness: Thomas J. Kopp


**UNION COUNTY SURVEYOR**

Date Received 9/9/14

Date Filed 9/9/14

Filed By Neil G. Miller

File Number 037-2014R



REGISTERED PROFESSIONAL LAND SURVEYOR

*Jeffrey S. Hsu*

OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2015

I used a steel tape and magnetic compass in the establishment of the accessories. I used 16° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the bearing trees. I use a Leica RTK GPS in tying the iron pins. Basis of bearing is as per Survey Number 025-2014.