## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

Corner originally established by Rufus S. Moore under GLO contract number 382, dated March 23, 1881. Surveyor General record states:

Set basalt stone 18x10x5 in mound of stone for ¼ sec cor from which; A pine 24 in. dia. bears N18°E, 99 lks dist.

Corner evidence found by Duane I. Griffith, OPLS 644, on Union County Survey number 23-80. His map states: Found mound of stone with 19"x10"x6" stone faintly marked  $\frac{1}{4}$ . Stump hole N18°E, 99 lks.

Corner remonumented by Barry B. Barbour, OPLS 1051, on Union Survey number 33-79. His map states: Corner monumented from original evidence. 2½" x 30" pipe & B.C. 24" Pine N43°W, 37.5 ft. 20" Pine S58°E, 47.8 ft.

Corner found and used on Union County Survey numbers 71-80 and 1-81 by Gregory T. Blackman, OPLS 991. His maps state: Found Brass Cap.


No record of subsequent monumentation found in Union County survey records.

## Description of corner evidence found:

Found  $2\frac{1}{2}$ " brass cap monument marked as shown:

Found 22" Ponderosa Pine S58°E, 47.8 feet with scribes visible. Found 26" Ponderosa Pine N43°W, 37.5 feet with scribes visible.

See Union County survey number 42-88



RLS 1051

DIAGRAM

T2N R39E

T-9

29

Description of monument and accessories I established to perpetuate the original location of this corner:

NONE

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 17, 1988
RICK G. ROBINSON
2219

UNION COUNTY SURVEYOR

Date Received 12-8-88

Date Filed 12-9-88

BY G. LANGLITZ DEPU

File No. 147-88 R

Form R6-7100-57 (9/71)

☆U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276