
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 2 N R 39 E T-16



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 025-2014

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, 30 inches in the ground, with 2 $\frac{1}{2}$ " aluminum cap marked as shown below, from which:

An 16 inch Ponderosa Pine bears South 44° East, a distance of 37.35 feet, marked CE 1/16 S27 BT.

An 15 inch Ponderosa Pine bears North 34° West, a distance of 50.45 feet, marked CE 1/16 S27 BT.

Set a steel fencepost approximately 1 foot North of corner monument. Corner falls approximately 7.3 feet Southwest of a fence corner.

I hereby certify that the corner was monumented on August 28, 2014.

Witness: Thomas J. Kopp

UNION COUNTY
SURVEYOR

Date Received 9914


Date Filed By 614

File Number 041-2014 R

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015



I used a steel tape and magnetic compass in the establishment of the accessories. I used 16° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the bearing trees.