


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner established by Barry Barbour in survey 33-79. Union County Survey Records state:
1 1/4" x 30" Pipe & B.C.
10" Pine N09°W, 24.0 ft.
10" Pine S83°E, 27.7 ft.

T 2 N R 39 E U-10



DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a 1" galvanized iron pipe with 2 1/2" brass cap, 9" above ground, marked as shown from which:
A 14" Ponderosa Pine bears North 83° East, a dist. of 27.7 ft., alive and vigorous with scribes visible on partially healed blaze. Bearing tree tag attached.
No evidence of North West BT, area has been heavily logged

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

NEW BEARING OBJECTS:

An 11" Ponderosa Pine bears North 24° West, a distance of 43.10 feet, marked SW 1/16 S28 BT. Monument falls in East/West fence line.

I hereby certify that the corner was perpetuated on May 29, 2018.


Witness: Kyle Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019



**UNION COUNTY
SURVEYOR**

Date Received 12/31/19
Date Filed 12/31/19
Filed By N. L. Gillman
File Number 074-2019R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.