UNION COUNTY CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.

S 28

No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established

See map of survey Number 025-90 filed in Union County Surveyors office.

Description of monument and accessories I established to perpetuate the

original location of this corner: At the proportionate position between the section corner West and the 1/4 corner East; I set a 5/8"x 30" rebar with plastic cap marked BGA SURVEY MARKER, 29 inches in the ground, from which:

New Bearing Trees; A 23 inch diameter Ponderosa Pine bears S 74°E, 29.70 feet marked W1/16 S33 BT A 12 inch diameter Larch bears N 30° W, 19.52 feet marked W1/16 S28 BT

A fence corner falls 1 foot South and 3 feet East of monumented corner.

Painted a 6 inch red band around all BTs and attached bearing tree signs.

I hereby certify that the above corner point was perpetuated as hereon described on August 10, 1990.

Witnesses: Larry Pitcher

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 991 to the BT blaze.



UNION COUNTY SURVEYOR
Date Received ///26/90
Date Filed 11/20/90 By Str on 1. Slock
File No. 67-90R

V-10