
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T2N R39EW-7



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 038-2021

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin, 28" in the ground, with 1 1/2" aluminum cap marked as shown, from which:

NEW BEARING OBJECTS:

A 13" Douglas Fir bears North 44° East a dist. of 11.35 ft., marked CN 1/16 S32 BT A 13" Douglas Fir bears South 72° West a dist. of 6.15 ft., marked CN 1/16 S32 BT

Set steel fence post approx. 0.2 feet Southeasterly

A North/South bearing fence line falls approx. 13 feet East

I hereby certify that the corner was monumented on August 4, 2021.

Witness: Kyle Tucker, Emmitt Ambert

SURVEY

MARKER

T2N R39E

CN 1/16 - S32

2021

OPLS 83571

PROFESSIONAL LAND SURVEYOR

June 2, 2010 JEFFREY S. HSU 83571

OREGON

Renewal Date: June 30, 2023

UNION COUNTY
SURVEYOR

Date Received BIBIZI

Date Filed BIBIZI

Filed By ULGULANDERTY

File Number 031-7271R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.