


UNION COUNTY
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established

See map of survey Number 025-90 filed in Union County Surveyors office.

Description of monument and accessories I established to perpetuate the

original location of this corner:

At the position determined by survey ; I set a 5/8"x 30" rebar with plastic cap marked BGA SURVEY MARKER, 29 inches in the ground, from which:

New Bearing Trees;

A 6 inch diameter Ponderosa Pine bears N 30°E, 48.83 feet marked X BT.

A 14 inch diameter Ponderosa Pine bears N 77° W, 83.92 feet marked NW1/16 S33 BT

Fence corner is 4.6 feet North and 13.5 feet West.

Painted a 6 inch red band around all BTs and attached bearing tree signs.

I hereby certify that the above corner point was perpetuated as hereon described on August 10, 1990.

Witnesses: Larry Pitcher

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 991 to the BT blaze.



UNION COUNTY SURVEYOR	
Date Received	<u>11/20/90</u>
Date	<u>11/20/90</u>
By	<u>Gregory T. Blackman</u>
File No.	<u>63-90R</u>