


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 2 N R 39 E W-14



DESCRIPTION OF CORNER EVIDENCE FOUND:

An unrecorded 5/8" iron pin, 10" above ground, in a collar of stone, falls North 71° East, a distance of 7.85 feet from position as determined by survey.

SEE SURVEY NUMBER 025-2014

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, 27 inches in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

A 5 inch Ponderosa Pine bears North 63° East, a distance of 55.10 feet, marked NW 1/16 S34 BT.


A 3 inch Ponderosa Pine bears North 87° West, a distance of 54.50 feet, marked X BT.

Set a steel fencepost approximately 1 foot North of corner monument.

I hereby certify that the corner was monumented on August 26, 2014.

Witness: Thomas J. Kopp

UNION COUNTY SURVEYOR	
Date Received	9/9/14
Date Filed	9/9/14
Filed By	<i>DLG/Muir</i>
File Number	045-2014R



REGISTERED PROFESSIONAL LAND SURVEYOR
<i>[Signature]</i>
OREGON June 2, 2010
JEFFREY S. HSU 83571

Renewal Date: June 30, 2015

I used a steel tape and magnetic compass in the establishment of the accessories. I used 16° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the bearing trees.