History of original corner establishment:

Corner not originally established

DIAGRAM **T2N R39E** CK S 33

Description of corner evidence found:

NONE


Description of monument and accessories I established to perpetuate the original location of this corner: At the corner position, I set a $2\frac{1}{2}$ inch x 30 inch aluminum pipe with aluminum cap marked as shown, 30 inches in the ground from which:

New BTs

A 25 inch diameter P.Pine bears N710E 89.6 feet marked C4 S33 BT A 24 inch diameter P.Pine bears N7°W, 13.0 feet marked C4 S33 BT

I used a steel tape and magnetic compass in the establishment of these accessories. I used 20° East magnetic declination. The distances to the bearing trees are to the center of the tree. I painted a 6 inch red band around the bearing trees and attached a bearing tree sign to each. I attached a brass washer marked OPLS 991 to the BT blaze of the bearing trees.

T2N R39E C 4 + S 33 1984 **OPLS 991**



Office of Coun	ty of	***************************************
State of, / hereby certify that the	within instrument was filed	in this office
for record on the day of , 19 , 19		Unional colors
(COUNTY OFFICIAL)	(DEPUTY)	- SURVEYOR
6-7100-57 (9/71)		Date Received 9-23-24

Form R

Date Filed 9.25-84 By G. LANGLITZ DEPUTY File No. 935-84R

SEE SURVEY 44-84